PUMP REPAIR SERVICE CO.

INVOICE

P.O.BOX 34327
SAN FRANCISCO, CA 94134
Phone: (415) 467-2150

Number	038340
Date	06/16/2017
Page	1

Bill To:	Ship To:
166782	SAME
SAN LEANDRO USD MAINTENANCE 1145 ALADDIN AVE SAN LEANDRO, CA 94577	SAN LEANDRO USD MAINTENANCE 1145 ALADDIN AVE SAN LEANDRO, CA 94577

Reference #	Shipped	Sls	Terms	Tax Code	Doc #	Wh	Ship Via
GREG DWYER	03/16/17	06	NET 30 DAYS	CAALCSL	D17764	01	PRSCO

Item	Description	Shipped	UM	Price	UM	Extension
	SAN LEANDRO HIGH					
	MOISTURE SEAL FAILURE LIGHT ON (1) PUMP NOT WORKING, TROUBLE-SHOOT, CONTROL PANEL IS BURNED FIXED OLD PANEL ON A TEMPORAY BASIS, ORDERD NEW PANE, FLOATS INSTALLED, TESTED & RAN TO SPEC.					
98	CONTROLLER PANEL	1	EA	7324.00	EA	7324.00
98	FLOATS	4	EA	169.40	EA	677.60
98	BRACKET FABBED	1	EA	64.20	EA	64.20
98	HARDWARE & MATERIALS	1	EA	122.75	EA	122.75
FF	FACTORY FREIGHT	1	EA	481.84	EA	481.84
80	FIELD LABOR TO PULL PUMP REPAIR & REINSTALL 53.3 HOURS @ $148.00 PER	1	EA	7888.00	EA	7888.00
81	SHOP LABOR 8.5 HOURS @ $118.00 PER	1	EA	1003.00	EA	1003.00
94	ELECTRICAL LABOR TO TROUBLE-SHOOT, TEMPORARY WIRING INSTALLED UNTIL NEW CONTROLLER PANAL IS RECIVED, CHANGED WITH NEW CONTROLLER PANEL, CHANGED FLOATS, TESTED UNIT	1	EA	7650.00	EA	7650.00
83	BOOM TRUCK (2) DAYS @ $750.00 PER	1	EA	1500.00	EA	1500.00
91	SERVICE TRUCK (1) DAY	1	EA	155.00	EA	155.00

Merchandise	Misc	Tax	Freight	Total Due
26384.55	481.84	845.36	.00	27711.75

SERVING THE BAY AREA SINCE 1941